

Equipment ID	Plant	Equipment Name	Device
E70751E-500-003240	SKI_C_P...	MOTOR-WINDER TRIM PULPER PUMP	

Problem	Possible Causes	Solution
Abnormal condition detected on MOTOR-WINDER TRIM PULPER PUMP SKI_C_PM16	<ul style="list-style-type: none"> Terminal looseness Contamination in the system Motor deterioration Stator open coil Phase loss Stator short turn 	<ul style="list-style-type: none"> Short - Term Solution <ul style="list-style-type: none"> Immediate Immediate Immediate Long - Term Solution <ul style="list-style-type: none"> Long-term maintenance or repair plan Long-term maintenance or repair plan Long-term maintenance or repair plan

References				
Electric Motor Maintenance and Troubleshooting.pdf	p.189	p.316	p.312	p.312




Smart Industrial solutions

MPRO

Total solutions for motors
A real-time monitoring, fault diagnostics, and automated recommendation system for analyzing motor failures.

INFRASTRUCTURE



Highlight Features

- Fault zone analysis (Power & Spectrum)
- Energy and efficiency optimization
- Recommendation action by genAI and expert consultant

Benefits

- Increase reliability of motor system (96% coverage of motor failures)
- Energy saving up to 30% from energy management

Contact Person

Mr. Thitipat Charoenkitsupat (Ball)
Sales Engineer

065 936 0775

Thitchar@scg.com

Ms. Supinya Supajam (Fan)
Manager - Smart Industrial Solutions

065 619 1536

Supinyas@scg.com

